



**ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ-1, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ, ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ**

ਵੱਲ

Principal,
Sita Grammar School,
Ludhiana Road, Malerkotla


ਨੰਬਰ 63

ਮਿਤੀ 29/03/26

ਵਿਸ਼ਾ: ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ (ਸਾਲ 2026-27) ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ SGS-M/2026-27/0101 ਮਿਤੀ 25.04.2026.


ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ, ਸ਼੍ਰੀ ਗੁਰਤੇਜ ਸਿੰਘ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2026-27 (31-03-2027) ਤੱਕ ਬਾਹਰੋਂ ਦੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ੀਨਲ ਅਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਹਾਂ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਉਣ ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਆਨਲਾਇਨ ਚਲਾਨ ਰਸੀਦ ਨੰਬਰ 23416632 ਮਿਤੀ 12/05/26 ਰਾਹੀਂ 20,000/ ਜਮਾਂ ਕਰਵਾ ਲਈ ਹੈ।
ਨੱਥੀ/ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ :1, ਲੋ:ਨਿ:ਵਿ:,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਦਫਤਰ ਦੇ ਪੱਤਰ ਨੰ: 733 ਮਿਤੀ 30-04-2026 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।



ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ :1, ਲੋ:ਨਿ:ਵਿ:,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ

Name of School:- Sita Grammar School, Ludhiana Road, Malerkotla.

As per report by Sh. Gurtej Singh, Junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Safety should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.

As per visually inspection as reported by the undersigned the above building may be used for normal use for One year up to 31/03/2027 subject to the above conditions.


Sub-Divisional Engineer,
Const. Sub Division No 1,
PWD, B&R Br., Malerkotla.